



**Hubshell**

135/142

148

157

**A** NDS Flange  $\varnothing$

47mm

47mm

47mm

**B** NDS Center to Flange

34mm

37mm

42mm

**C** DS Center to Flange

21mm

24mm

29mm

**D** DS Flange  $\varnothing$

60mm

60mm

60mm

\*\*Positive 1.5mm offset\*\*

\*For Flange to Dropout Value Subtract Center to Flange Value from 1/2 of Dropout Spacing\*